

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name HYDEEN, BRAD	Case Number BP24012501	Date of Crash 12/23/2024	Time 10:45 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM
Road of Occurrence W 82ND ST		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) CAJAMARCA PUMA, JAIME, GUSTAVO	Address (Street, City, State, Zip) 6280 SUMTER AVE N, MINNEAPOLIS, MN 554282835	
	DOB 2/5/1981	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	
	Passenger Name DIRCIO ABARCA, ANGELICA	Passenger Injury POSSIBLE INJURY (C)	Passenger DOB 10/18/1979	
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported Not Transported	Passenger Age 45		
Passenger Name CAJAMARCA-DIRCIO, JAIME, CRISTINO	Passenger Injury NO APPARENT INJURY	Passenger DOB 6/23/2017		
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported	Passenger Age 7		
Passenger Name DIRCIO-MATEOS, EDGAR, ALEXANDER	Passenger Injury NO APPARENT INJURY	Passenger DOB 7/11/2013		
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported	Passenger Age 11		

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) KRAMER, BLAKE, WILLIAM	Address (Street, City, State, Zip) 7804 TITAN CT, PASADENA, MD 21122	
	DOB 9/20/1990	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

Veh 1 was Eastbound on 82nd St W approaching the 35W exit and entrance. Veh 2 was Westbound 82nd St W through the green light. Veh 1 made a left turn (NB) through the yellow flashing arrow. Veh 1 failed to yield right of way to Veh 2. Both cars collided causing substantial damage to both vehicles. Veh 1 is at fault for causing the crash.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER MATTHEWS, NICHOLAS	Case Number BP24012555	Date of Crash 12/24/2024	Time 06:25 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence 15TH AVE S		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) RUDIE, LYNSIE, MARIE	Address (Street, City, State, Zip) 1792 HAWTHORNE AVE E, SAINT PAUL, MN 551194512	
	DOB 6/17/1986	Sex F	Injury NO APPARENT INJURY	Safety Equipment UNKNOWN
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

UNIT 2	Person Type	Name (Last,First,Mi)	Address (Street, City, State, Zip)	
	DOB	Sex	Injury NO APPARENT INJURY	Safety Equipment
	Transported	Alcohol Test	Alcohol Test Result	

On 12/25/2024, I responded to an accident that occurred on 15th Ave S 1825 hours. The accident occurred in front of the address 8841 15th Ave S.

The driver of unit 1 stated that they were driving Northbound on 15th Ave S. The driver said that the bright headlights of traffic traveling Southbound caused them to misjudge the amount of space needed for Southbound traffic. The misjudgment caused the driver to drive closer to the east side of the street, where an unoccupied unit 2 was parked.

Unit 1 struck unit 2 with its front passenger side bumper. The damage that unit 1 incurred was to its front bumper, the passenger side wheel well was damaged and smashed in completely, and the front passenger wheel was off its rim. No injuries were recorded to the driver of unit 1. The damage unit 1 incurred made it unable to drive.

Unit 2 was legally parked on the East side of the road. The damage to unit 2 includes: the rear bumper was smashed in completely and hanging off the vehicle, the driver side wheel well was damaged, the driver side rear tire was deflated. Unit 1 struck unit 2 with enough force to smash out completely the rear windshield. Unit 2 was not able to drive as well.

Unit 1 was towed by Chief's to their lot. Unit 2 called a private tow.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER RODRIGUEZ, DAVID	Case Number BP24012621	Date of Crash 12/27/2024	Time 12:23 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence KILLEBREW DR 300 FEET West From Its Intersection With KILLEBREW DRIVE AND 20TH AV		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) GRANT, LEAH, MARIA	Address (Street, City, State, Zip) 10355 TAYLOR ST NE, BLAINE, MN 554347613	
	DOB 2/7/2005	Sex F	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) CHILPE, ESCANDON, MARINA	Address (Street, City, State, Zip) 17701 KENYON AVE TRLR 63, LAKEVILLE, MN 550447235	
	DOB 11/6/1984	Sex F	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

Passenger Name LANGUREN CHILPE, ALEX	Passenger Injury NO APPARENT INJURY	Passenger DOB 1/25/2012
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported	Passenger Age 12
Passenger Name LANGUREN CHILPE, JOSHUA	Passenger Injury NO APPARENT INJURY	Passenger DOB 9/29/2016
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported	Passenger Age 8
Passenger Name LANGUREN CHILPE, MIGUEL	Passenger Injury NO APPARENT INJURY	Passenger DOB 3/16/2007
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported	Passenger Age 17
Passenger Name LANGUREN CHILPE, MARISOL	Passenger Injury NO APPARENT INJURY	Passenger DOB 12/14/2008
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported	Passenger Age 16

Unit 1 was traveling eastbound on Killibrew DR in the left hand turn lane.

Unit 2 was traveling eastbound on Killibrew DR in the straight lane.

Unit 2 attempted to change lanes into the left hand turn lane and sideswiped Unit 1.

Driver of Unit 2 could not provide proof of insurance, and was cited for no proof of insurance.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name PATROL MURPHY, JACOB	Case Number BP24012624	Date of Crash 12/27/2024	Time 01:50 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence E MALL RAMP		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) ALT, BRANDON, JOSEPH	Address (Street, City, State, Zip) 6405 HARKNESS AVE S, COTTAGE GROVE, MN 55016	
	DOB 9/19/1998	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) RAUSCH, MATTHEW	Address (Street, City, State, Zip) 1800 WEST OLD SHAKOPEE ROAD, BLOOMINGTON, MN 55431	
	DOB	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

Witness Information:

Name MURPHY, JACOB JAMES	Sex M
-----------------------------	----------

Unit one was backing up in a private parking lot (MOA East ramp) while Unit two was stationary directly behind it. Unit one was backing and not stopping. Unit two attempted to put his vehicle in reverse but was unable to do so in time. Due to Unit one not being able to stop in time or unable to see Unit two stationary right behind his vehicle, Unit one struck Unit two. Unit one's rear bumper struck Unit two's brush guard, causing minor damage to the brush guard. The driver of Unit one exited his vehicle and stated he was sorry, and did not see Unit two. No injuries to either driver.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER SAGER, SCOTT	Case Number BP24012627	Date of Crash 12/27/2024	Time 04:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence At the Intersection of PORTLAND AVE S And AMERICAN BLVD E		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) LOPEZ, HERRERA, VIANEY	Address (Street, City, State, Zip) 710 E 78TH ST APT 302, RICHFIELD, MN 554234492	
	DOB 3/14/1992	Sex F	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) KENNETH, BACKE, THOMAS	Address (Street, City, State, Zip) 1614 OAK HILLS DR, COLORADO SPRINGS, CO 80919	
	DOB 10/31/1992	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	
Passenger Name NELSON, ANA, MARIE JOY		Passenger Injury NO APPARENT INJURY		Passenger DOB 8/24/1993
Passenger Safety Equipment LAP AND SHOULDER BELT USED		Transported		Passenger Age 31

Both units were eastbound on American Blvd E. There was another crash in the intersection at the time. Unit 2 said that he stopped and was rear ended by Unit 1. Unit 1 stated she was trying to make a left turn and hit unit 2. Unit 1 did not have insurance or a driver's license and stated she just got the car. Unit 2 was issued a citation for no driver's license and no insurance.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER HART, NICHOLAS	Case Number 24012632	Date of Crash 12/27/2024	Time 05:25 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence At the Intersection of LINDAU LN And 22ND AVE		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) MEDINA RAYMUNDO, ANGEL	Address (Street, City, State, Zip) 8818 OLD CEDAR AVE S APT 3, BLOOMINGTON, MN 554251580	
	DOB 3/8/2007	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	
	Passenger Name RAYMUNDO NAVARRO, BLANCA, ESTELA	Passenger Injury SUSPECTED MINOR INJURY (B)	Passenger DOB 1/1/1974	
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported EMS Ground	Passenger Age 50		
Passenger Name MEDINA, ALEXIS	Passenger Injury POSSIBLE INJURY (C)	Passenger DOB 12/9/2010		
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported EMS Ground	Passenger Age 14		
Passenger Name MEDINA, LUNA	Passenger Injury NO APPARENT INJURY	Passenger DOB 7/10/2014		
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported	Passenger Age 10		

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) KENEFICK, PETER, RICHARD	Address (Street, City, State, Zip) 13423 COACHFORD WAY, ROSEMOUNT, MN 550686167	
	DOB 8/19/1970	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

Unit 1 was in westbound lane turning left (south). Unit 2 was traveling eastbound. When unit 1 was turning left, unit 2 was traveling east and unit 1 hit unit 2 on the driver side.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name GARZA, RAUL	Case Number 24012640	Date of Crash 12/27/2024	Time 10:14 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence E OLD SHAKOPEE RD		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) MUMIN, IBRAHIN, AHMED	Address (Street, City, State, Zip) 1818 14TH AVE S APT 35, MINNEAPOLIS, MN 554042108	
	DOB 9/11/1989	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) VONDERHARR, MICHAEL, JEROME	Address (Street, City, State, Zip) 1800 W OLD SHAKOPEE RD, BLOOMINGTON, MN 554313071	
	DOB 3/11/1977	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

Unit 1 was stopped at a red light in the left lane traveling east on Old Shakopee Rd. Unit 2 (unmarked police squad car) was stopped at a red light in the right lane. An unknown vehicle in the intersection stopped, trying to get turned around. The unknown vehicle then got turned around and was facing WB. The vehicle accelerated over the cement median and struck a roadway sign. Unit 2 attempted to make a U turn to initiate a stop on the unknown vehicle. As Unit 2 started its turn, Unit 1 began proceeding through the intersection. Unit 2 stopped, at which time Unit 1 struck the drivers side doors with its front passenger side fender. Both vehicles stopped and exchanged information.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER SAGER, SCOTT	Case Number BP24012648	Date of Crash 12/28/2024	Time 07:43 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM
Road of Occurrence At the Intersection of E 82ND ST And 12 AVE S		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) HASSAN, ABDURAHMAN, MAHAMED	Address (Street, City, State, Zip) 102 W DIAMOND LAKE RD #124, MINNEAPOLIS, MN 55419	
	DOB 3/13/1985	Sex M	Injury POSSIBLE INJURY (C)	Safety Equipment LAP AND SHOULDER BELT USED
	Transported Not Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) KOLLANDER, JASON, CHRISTOPHER	Address (Street, City, State, Zip) 8418 COLUMBUS AVE S, BLOOMINGTON, MN 554202458	
	DOB 10/31/1970	Sex M	Injury SUSPECTED MINOR INJURY (B)	Safety Equipment LAP AND SHOULDER BELT USED
	Transported EMS Ground	Alcohol Test No, Test Not Given	Alcohol Test Result	
	Passenger Name KOLLANDER, JORDAN, MICHELLE	Passenger Injury SUSPECTED MINOR INJURY (B)	Passenger DOB 4/14/2001	
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported EMS Ground	Passenger Age 23		

UNIT 2 WAS NORTHBOUND ON 12 AVE S AND SAID THAT THEY WERE T-BONED. THERE IS NO STOP SIGN FOR NORTHBOUND 12 AVE. UNIT 1 WAS WESTBOUND ON 82 ST W AND SAID HE HIT THE OTHER VEHICLE AND DID NOT SEE THE STOP SIGN. I ALSO OBSERVED THAT UNIT 1 HAD TINT ON ITS WINDSHIELD AND SIDE WINDOWS. UNIT 2 ROLLED ONTO ITS SIDE AFTER THE IMPACT AND FIRE HAD TO EXTRACATE ITS OCCUPANTS. UNIT 2'S DRIVER AND PASSENGER WERE BOTH TRANSPORTED BY PARAMEDICS TO THE HOSPITAL. UNIT 1 STATED THEY HAD LEG PAIN, BUT DECLINED TRANSPORT. UNIT 1 ISSUED CITATION FOR STOP SIGN VIOLATION.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER SAGER, SCOTT	Case Number BP24012664	Date of Crash 12/28/2024	Time 03:15 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence SE MALL BELTWAY		City Bloomington	County HENNEPIN	

UNIT 1	Person Type	Name (Last,First,Mi)	Address (Street, City, State, Zip)	
	DOB	Sex	Injury	Safety Equipment
	Transported	Alcohol Test	Alcohol Test Result	

UNIT 2	Person Type	Name (Last,First,Mi)	Address (Street, City, State, Zip)	
	DOB	Sex	Injury	Safety Equipment
	Transported	Alcohol Test	Alcohol Test Result	

Passenger Name	Passenger Injury	Passenger DOB
FURZLAND, ABLE, JOHN	NO APPARENT INJURY	1/30/2016
Passenger Safety Equipment	Transported	Passenger Age
LAP AND SHOULDER BELT USED		8
Passenger Name	Passenger Injury	Passenger DOB
FURZLAND, FREYA, TIANA	NO APPARENT INJURY	8/17/2018
Passenger Safety Equipment	Transported	Passenger Age
BOOSTER SEAT PROPERLY		6

Unit 1 and Unit 2 were both westbound on the ring road at the Mall of America. They were on the south side of the mall between the Radisson Blu and gate 2 exit. Unit 2 reported stop and go traffic. Unit 2 was rear ended by Unit 1. Unit 2 said that he pulled over and put his flashers on. Unit 1 then went around him and continued on. Unit 2 was able to take a photograph of Unit 1 and said he saw the driver was a female.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name PATROL SMITH, MICHAEL	Case Number 24012673	Date of Crash 12/28/2024	Time 05:54 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence E MALL RAMP		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) FOSTER, AJA, JAH NICOLE	Address (Street, City, State, Zip) 8691 OLD STATE ROAD 60 UNIT 106, SELLERSBURG, IN 47172	
	DOB 12/3/2002	Sex F	Injury NO APPARENT INJURY	Safety Equipment UNKNOWN
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) CALDERON, NATHAN, MANUEL	Address (Street, City, State, Zip) 426 OAK ST, HUDSON, WI 54016	
	DOB 9/16/1987	Sex M	Injury NO APPARENT INJURY	Safety Equipment UNKNOWN
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

Unit 2 at stoplight to exit Gate 5 of Mall of America onto 24th Av. Unit 1 was directly in front of Unit 2 and all of a sudden backed up striking Unit 2. Unit 1 then left the scene failing to stop or provide information. No injuries.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER BALGOBIN-DIAZ, ANGELICA	Case Number BP24012680	Date of Crash 12/28/2024	Time 10:26 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence OLD CEDAR AVE 100 FEET South From Its Intersection With 80TH ST E		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) MOHAMED, SADIA, ABDI	Address (Street, City, State, Zip) 9910 DREW AVE S APT 110, BLOOMINGTON, MN 55431	
	DOB 9/15/1994	Sex F	Injury SUSPECTED MINOR INJURY (B)	Safety Equipment LAP AND SHOULDER BELT USED
	Transported EMS Ground	Alcohol Test No, Test Not Given	Alcohol Test Result	
	Passenger Name FARAH, FARAH, ELMI	Passenger Injury SUSPECTED MINOR INJURY (B)	Passenger DOB 1/1/1993	
	Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported EMS Ground	Passenger Age 31	

Property Damage Information:

Agency/Organization	Property Description WOOD LIGHT/UTILITY POLE SPLIT FROM BASE	Property Type PUBLIC	Yellow Tag # BP24012680	Owned By: UNKNOWN
---------------------	---	-------------------------	----------------------------	----------------------

On 12/28/2024 at approximately 2226 hours, I, Officer Balgobin-Diaz #392 responded to the area of 80th St E and Old Cedar Ave S on reports of a vehicle crashed into a utility pole.

Upon my arrival, I observed a single vehicle displaying MN Plate #EBD853, collided head on with a utility pole just south of the intersection.

Driver stated she was traveling southbound on Old Cedar Ave S from American Blvd.

Driver stated she did not believe her brakes were working appropriately.

Driver stated she observed a vehicle coming towards them and lightly pressed on her brakes but did not want to press all the way down.

Driver was unclear why she crashed into the pole instead of continuing on the straightaway southbound on Old Cedar Ave S.

Driver is 5 months pregnant and complained of leg pain.

Passenger complained of knee pain and stated he believed he hit his head on the dashboard.

Both transported to the hospital via Allina Paramedics.

No witnesses of the crash on scene.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name GARZA, RAUL	Case Number BP24012713	Date of Crash 12/29/2024	Time 09:42 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence BLOOMINGTON AVE S		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) CARTER, DIMAGGIO, LAVON	Address (Street, City, State, Zip) 8110 BLOOMINGTON AVE, BLOOMINGTON, MN 554251108	
	DOB 8/22/2006	Sex	Injury NO APPARENT INJURY	Safety Equipment UNKNOWN
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

UNIT 2	Person Type	Name (Last,First,Mi)	Address (Street, City, State, Zip)	
	DOB	Sex	Injury NO APPARENT INJURY	Safety Equipment
	Transported	Alcohol Test	Alcohol Test Result	

UNIT 3	Person Type	Name (Last,First,Mi)	Address (Street, City, State, Zip)	
	DOB	Sex	Injury NO APPARENT INJURY	Safety Equipment
	Transported	Alcohol Test	Alcohol Test Result	

Property Damage Information:

Property Owner Name GEORGETOWN PARK	Property Description GARAGE BUILDING/DOORS	Property Type PRIVATE		
--	---	--------------------------	--	--

Unit 1 did not know if he had put the vehicle in park. Unit 1 backed into the garage building, striking two garage doors and the center wall of the garage. This caused the garage doors and walls to fall on top of Unit 2 and 3 that were parked in the garage. Unit 1 then pulled forward into a parking space. The driver of Unit 1 then went to his residence. When bystanders attempted to knock on the door, the driver of unit 1 did not respond.

Unit 2 and Unit 3 were both in the garage when Unit 1 hit the garage. Unit 2 and 3 were not occupied at the time. When officers knocked on Unit 1's door he came to the door. The driver of Unit 1 stated he was driving Unit 1 and caused the damage to the garage building.

Unit 1 provided insurance information. He received a citation for hit and run.

Unit 2 was not able to provide insurance information at this time, because the card was in the vehicle and the garage was laying on top of it. Unit 2 stated they would call once they were able to provide the information.

Unit 3 stated they did not have insurance on the vehicle.