

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency <b>BLOOMINGTON POLICE DEPT</b>	Officer Name <b>OFFICER MERSETH, DANIEL</b>	Case Number <b>25002559</b>	Date of Crash <b>03/24/2025</b>	Time <b>08:20</b> <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM
Road of Occurrence <b>YUKON AVE S</b>		City <b>Bloomington</b>	County <b>HENNEPIN</b>	

<b>UNIT 1</b>	Person Type <b>DRIVER</b>	Name (Last,First,Mi) <b>OSBORN, LAUREN, MAHONEY</b>	Address (Street, City, State, Zip) <b>2770 CLOVER PRESERVE DR, CHASKA, MN 553183234</b>	
	DOB <b>10/28/2008</b>	Sex <b>F</b>	Injury <b>SUSPECTED MINOR INJURY (B)</b>	Safety Equipment <b>LAP AND SHOULDER BELT USED</b>
	Transported <b>Not Transported</b>	Alcohol Test <b>No, Test Not Given</b>	Alcohol Test Result	

<b>UNIT 2</b>	Person Type <b>DRIVER</b>	Name (Last,First,Mi) <b>KPARKAH, PRINCESS, HAWA</b>	Address (Street, City, State, Zip) <b>11130 20TH ST NE, SAINT MICHAEL, MN 553764203</b>	
	DOB <b>11/28/1976</b>	Sex <b>F</b>	Injury <b>SUSPECTED MINOR INJURY (B)</b>	Safety Equipment <b>LAP AND SHOULDER BELT USED</b>
	Transported <b>EMS Ground</b>	Alcohol Test <b>No, Test Not Given</b>	Alcohol Test Result	

### Witness Information:

Name <b>KAPPLER, CHAD WILLIAM</b>	Sex <b>M</b>
--------------------------------------	-----------------

Unit 1 was n/b Yukon Ave waiting to make a left turn to w/b Old Shakopee Rd. Unit 1 was at a stop sign.  
Unit 2 was e/b Old Shakopee Rd in the right lane at Yukon Ave S. Unit 2 did not have a stop sign.  
Unit 1 pulled out in front of unit 2 causing an accident.

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name BROADHEAD, BAILEY	Case Number BP25002595	Date of Crash 03/25/2025	Time 08:30 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM
Road of Occurrence -- NOT ON ROADWAY -- 500 FEET North From Its Intersection With AMERICAN BLVD/GRAND AVE		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type	Name (Last,First,Mi)	Address (Street, City, State, Zip)	
	DOB	Sex	Injury	Safety Equipment
	Transported	Alcohol Test	Alcohol Test Result	

<b>UNIT 2</b>	Person Type DRIVER	Name (Last,First,Mi) CAMPBELL, SE'NIYYA, KAREN	Address (Street, City, State, Zip) 991 GALTIER ST APT 2, SAINT PAUL, MN 551175151	
	DOB 8/23/2003	Sex F	Injury NO APPARENT INJURY	Safety Equipment UNKNOWN
	Transported	Alcohol Test Unknown	Alcohol Test Result	

Unit 1 was parked facing eastbound in the parking lot. Unit 2 was traveling southbound in the parking lot. While traveling southbound, Unit 2 struck Unit 1. The front of Unit 2 struck Unit 1. Unit 1 sustained damages to the driver's side front quarter panel and headlight. Unit 1 was moved from the parking space to a slanted position, facing southeast.

The identifiable information of Unit 2 is a Blue Buick SUV with what appeared to be a Minnesota temporary tag on the rear of the vehicle.

#310 Follow-up. Suspect Vehicle identified via CCTV Surveillance. Suspect Veh 2 LSJ897, displaying temp plate 03666935. Driver identified as SeNiyah Campbell. Spoke with Campbell on the phone (recorded) and she admitted to the hit and run and claimed she didn't stop or leave any information because she was scared. She was mailed a citation for Hit and Run, DAR

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name HAEG, KYLE	Case Number BP25002629	Date of Crash 03/26/2025	Time 07:01 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence At the Intersection of PENN AVE S And AMERICAN BLVD		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type DRIVER	Name (Last,First,Mi) MALINSKI, ABBY, MARIE	Address (Street, City, State, Zip) 7004 JAMES AVE S, RICHFIELD, MN 554232949	
	DOB 12/17/1983	Sex F	Injury NO APPARENT INJURY	Safety Equipment UNKNOWN
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	
	Passenger Name LINDQUIST, ETHAN, LYNN	Passenger Injury NO APPARENT INJURY	Passenger DOB 4/13/2022	
Passenger Safety Equipment CHILD RESTRAINT SYSTEM - FORWARD FACING	Transported	Passenger Age 2		
Passenger Name LINDQUIST, NORA, KAY	Passenger Injury NO APPARENT INJURY	Passenger DOB 4/18/2019		
Passenger Safety Equipment CHILD RESTRAINT SYSTEM - FORWARD FACING	Transported	Passenger Age 5		

<b>UNIT 2</b>	Person Type DRIVER	Name (Last,First,Mi) PETERSON, TERRI, LYN	Address (Street, City, State, Zip) 8425 4TH AVE S, BLOOMINGTON, MN 554202349	
	DOB 7/21/1967	Sex F	Injury SUSPECTED MINOR INJURY (B)	Safety Equipment UNKNOWN
	Transported EMS Ground	Alcohol Test No, Test Not Given	Alcohol Test Result	

<b>UNIT 3</b>	Person Type DRIVER	Name (Last,First,Mi) COCHRAN-TROTTMAN, GEORGETTE, MARIA	Address (Street, City, State, Zip) 622 HYACINTH AVE E APT 4, SAINT PAUL, MN 551303594	
	DOB 7/18/1964	Sex F	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

### Property Damage Information:

Agency/Organization City of bloomington	Property Description SIGN ON MEDIAN	Property Type PUBLIC	Yellow Tag # BP25002629	Owned By: CITY
--	--	-------------------------	----------------------------	-------------------

### Witness Information:

Name JOSHI, SANGITA	Sex F
------------------------	----------

Unit 1 was traveling northbound on Penn Ave S in the far right lane. Driver of Unit 1 told officers that she had turned around due to her children in the backseat getting into an argument. When she turned back towards the front she had entered the intersection at American Blvd, and struck unit 2. Driver of unit 1 told officers that she thought she had a green light, however a person on the scene had told her it was red. No one in unit 1 had any apparent injuries reported on scene.

Unit 2 was traveling eastbound on American Blvd. Driver of unit 2 stated that she was traveling through the intersection with Penn Ave S when she was struck. Driver of unit 2 reported having pain in her chest, middle back, and lower right back. She was transported to the hospital by paramedics.

Unit 3 was a metro mobility bus. Driver of Unit 3 stated that she was stopped in the far left left turn lane to go south on Penn Ave S from westbound American BLvd W. She did not see the crash but a vehicle hit the driver's side of her bus.

Witness 1 was stopped at a red light traveling northbound on Penn Ave S in the far left northbound lane. Unit 1 passed her to her right entering the intersection at the red light, striking unit 2.

The impact of the crash appeared to have caused unit 2 to strike a roadway sign that was on the median on the east side of the intersection. The sign was knocked down and broken.

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name HYDEEN, BRAD	Case Number BP25002641	Date of Crash 03/27/2025	Time 09:25 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM
Road of Occurrence NORTHWEST CT		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type DRIVER	Name (Last,First,Mi) SCHETNAN, DAISY, CYNTHIA	Address (Street, City, State, Zip) 1006 MAPLE ST, NORTHFIELD, MN 550572917	
	DOB 7/9/2006	Sex F	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

<b>UNIT 2</b>	Person Type NON-MOTORIST	Name (Last,First,Mi) WACHOLZ, DEAN, BRADLEY	Address (Street, City, State, Zip) 1416 S GERMAN ST APT 1, NEW ULM, MN 560733483	
	DOB 4/13/1963	Sex M	Injury POSSIBLE INJURY (C)	Safety Equipment NONE
	Transported Not Transported			

Veh 1 pulling into parking ramp at Mall of America (Level P1 West Mid North end). Pedestrian walking in ramp towards sidewalk. Veh 1 bumped Pedestrian. Veh 1 driver stated she didn't see him until after she already bumped into him. Pedestrian refused all medical.



# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER LEBARON, KENNETH	Case Number 25002644	Date of Crash 03/27/2025	Time 10:26 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM
Road of Occurrence FRANCE AVE S		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type DRIVER	Name (Last,First,Mi) GRIMMER, DENNIS, JAMES	Address (Street, City, State, Zip) 9243 4TH AVE S, BLOOMINGTON, MN 554203721	
	DOB 10/9/1941	Sex M	Injury NO APPARENT INJURY	Safety Equipment UNKNOWN
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

<b>UNIT 2</b>	Person Type DRIVER	Name (Last,First,Mi) VOIGTS, SARA, LINN	Address (Street, City, State, Zip) 5813 W 61ST ST, EDINA, MN 554361929	
	DOB 3/7/1978	Sex F	Injury NO APPARENT INJURY	Safety Equipment UNKNOWN
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

### Witness Information:

Name PEARCE, JESSICA NICOLE	Sex F
--------------------------------	----------

v1 was n/b france in the right lane, coming up to American blvd and was going to go n/b through the intersection. v2 was s/b and turning to go e/b onto American blvd. v1 ran the red light and struck v2 at an angle (t-bone). v2 had the green turn arrow. v1 had a red light. witness statement was from a veh that was next to v2 in the turn lane next to her. witness statement was the same as v2's. v1 cited for fail to obey signal. both v's towed by chiefs. driver's exchanged info at the scene.

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name HYDEEN, BRAD	Case Number BP25002654	Date of Crash 03/27/2025	Time 02:41 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence 106TH ST W		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type DRIVER	Name (Last,First,Mi) BRANDBERG, LAWRENCE, CHARLES	Address (Street, City, State, Zip) 7500 EDINBOROUGH WAY APT 3309, EDINA, MN 554355613	
	DOB 10/24/1942	Sex M	Injury POSSIBLE INJURY (C)	Safety Equipment LAP AND SHOULDER BELT USED
	Transported EMS Ground	Alcohol Test No, Test Not Given	Alcohol Test Result	

<b>UNIT 2</b>	Person Type DRIVER	Name (Last,First,Mi) ISRAEL, OLIVER, IHEANYI	Address (Street, City, State, Zip) 10932 EWING AVE S, BLOOMINGTON, MN 554313642	
	DOB 9/20/1982	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

Veh 1 WB 106th to SB Morgan Av S. Veh 2 EB 106th. Veh 1 failed to yield right of way and turned in front of Veh 2 causing the crash.

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name MARTINEZ-SANCHEZ, MARIE	Case Number BP25002663	Date of Crash 03/27/2025	Time 05:28 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence At the Intersection of W 102ND ST And NORMANDALE BLVD		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type DRIVER	Name (Last,First,Mi) MELANDER, JEREMY, WALDEN	Address (Street, City, State, Zip) 7663 WEDGEWOOD CT N, MAPLE GROVE, MN 553112810	
	DOB 3/13/1973	Sex M	Injury POSSIBLE INJURY (C)	Safety Equipment LAP AND SHOULDER BELT USED
	Transported EMS Ground	Alcohol Test No, Test Not Given	Alcohol Test Result	

<b>UNIT 2</b>	Person Type DRIVER	Name (Last,First,Mi) BANKS, COREY, HARRELL LAMAR	Address (Street, City, State, Zip) 10700 BRUNSWICK RD APT 105, BLOOMINGTON, MN 554381858	
	DOB 10/24/1982	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

<b>UNIT 3</b>	Person Type DRIVER	Name (Last,First,Mi) CHOV, MEY, HANN	Address (Street, City, State, Zip) 7208 LAKEVIEW CIR, BLOOMINGTON, MN 554381532	
	DOB 8/18/1980	Sex F	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

Passenger Name OSBURN, ELEANOR, PAN-PAN	Passenger Injury NO APPARENT INJURY	Passenger DOB
Passenger Safety Equipment BOOSTER SEAT PROPERLY	Transported	Passenger Age

Unit 1 was heading southbound on Normandale Blvd turning eastbound on to 102nd ST W. Unit 2 was heading Southbound on Normandale. Both vehicles collided in the intersection. Both vehicles had a yellow light. Unit 3 was behind Unit 1 and was heading southbound Normandale Blvd turning westbound on to 102nd ST W unable to stop in time and crashed in to unit 1.

Unit 1 had front damage to vehicle and Unit 2 had damage to the driver front side. Unit 3 had minor damage. Unit 1 and 2 had airbags deployed.

Unit 1 and Unit 2 were towed.

Driver from Unit 1 was transported to hospital for further evaluation.

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name HAEG, KYLE	Case Number BP25002669	Date of Crash 03/27/2025	Time 04:55 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence At the Intersection of AMERICAN BLVD W And NICOLLET AVE S		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type DRIVER	Name (Last,First,Mi) BEANE, NATHAN, ALLAN	Address (Street, City, State, Zip) 8208 ABBOTT AVE S, BLOOMINGTON, MN 554311024	
	DOB 7/14/1980	Sex M	Injury NO APPARENT INJURY	Safety Equipment UNKNOWN
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

<b>UNIT 2</b>	Person Type DRIVER	Name (Last,First,Mi) STALLONE, DIANA, LEE	Address (Street, City, State, Zip) 7956 LYNDAL AVE S APT 118, BLOOMINGTON, MN 554201133	
	DOB 10/23/1955	Sex F	Injury NO APPARENT INJURY	Safety Equipment UNKNOWN
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

Unit 1 was Eastbound American Blvd in the far-left turn lane at the stoplight to go Northbound on Nicollet Ave S when unit 2 hit unit 1 on the rear bumper.

unit 2 was also Eastbound American Blvd in the far-left turn lane behind unit 1 to go Northbound on Nicollet Ave S prior to the crash.

Both unit 1 and unit 2 were at stopped at the red light before turning Northbound on Nicollet Ave S.



# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name HANSON, LAUREN	Case Number 25002674	Date of Crash 03/27/2025	Time 09:33 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence 12TH AVE S		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type DRIVER	Name (Last,First,Mi) MOHAMED, HALIMO, ALI	Address (Street, City, State, Zip) 8735 PORTLAND AVE S, BLOOMINGTON, MN 55420	
	DOB 1/1/1986	Sex F	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	
	Passenger Name MOHAMED, IKRAM, ABDI RAHMAN	Passenger Injury SUSPECTED SERIOUS INJURY (A)	Passenger DOB 5/1/2008	
	Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported EMS Ground	Passenger Age 16	

<b>UNIT 2</b>	Person Type DRIVER	Name (Last,First,Mi) SUTPHEN, DREW, JONATHAN	Address (Street, City, State, Zip) 580 MARSHALL AVE, SAINT PAUL, MN 55102	
	DOB 7/9/1987	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

### Witness Information:

Name RAE, BROADHEAD BAILEY	Sex F
-------------------------------	----------

Unit 1 traveling WB on 86th St. E. approaching 12th Ave S. Unit 2 traveling EB on 86th St. E. approaching approaching 12th Ave. S. Unit 2 had right of way and proceeded into the intersection. Unit 1 also proceeded into the intersection where impact was made. Unit 2 impacted Unit 1 on the passenger side. Front right passenger in Unit 1 had injury to the right arm, possibly broken and was transported to the hospital. Unit 2 was towed due to disabling vehicle.

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER SAGER, SCOTT	Case Number 25002700	Date of Crash 03/28/2025	Time 04:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence LYNDALE AVE S 40 FEET South From Its Intersection With 94 ST W		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DOB	Sex	Injury		Safety Equipment
	Transported	Alcohol Test		Alcohol Test Result	

<b>UNIT 2</b>	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DOB	Sex	Injury		Safety Equipment
	Transported	Alcohol Test		Alcohol Test Result	

Unit 2 was backed into by Unit 1 while in a parking lot. Unit 1 left the scene and did not provide information to unit 2. Unit 2 had damage to the passenger side brake light. Unit 1 driver was described as a 75 year old white male.

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name MITCHELL, E-DON	Case Number BP25002744	Date of Crash 03/29/2025	Time 03:40 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence NORTHWEST CT		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type DRIVER	Name (Last,First,Mi) BENSON, LAURA, ROSE	Address (Street, City, State, Zip) 3421 15TH AVE S APT 2, MINNEAPOLIS, MN 554072272	
	DOB 11/19/1992	Sex F	Injury NO APPARENT INJURY	Safety Equipment UNKNOWN
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

<b>UNIT 2</b>	Person Type DRIVER	Name (Last,First,Mi) PAGOUNI, MARIA, MADALENA	Address (Street, City, State, Zip) 6831 WOODDALE AVE S, EDINA, MN 554351660	
	DOB 12/26/1998	Sex F	Injury NO APPARENT INJURY	Safety Equipment UNKNOWN
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

Passenger Name ELEFThERIOU, MARIA, MICHAEL	Passenger Injury NO APPARENT INJURY	Passenger DOB 2/10/1972
Passenger Safety Equipment UNKNOWN	Transported	Passenger Age 53

### Witness Information:

Name ELEFThERIOU, MARIA MICHAEL	Sex F
------------------------------------	----------

VEH 1 CRASHED INTO VEH 2 WHILE EXITING A PARKING RAMP. VEH 1 FRONT OF VEHICLE HIT VEH 2 REAR OF VEHICLE (REAR ENDED TYPE CRASH). VEH 1 LEFT THE SCENE WITHOUT EXCHANGING INFORMATION. MINIMAL DAMAGE TO VEH 2 REAR PASSENGER-SIDE.

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name POLICE OFFIC KOLOSHUK, DASHA	Case Number BP250022752	Date of Crash 03/29/2025	Time 03:20 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence E MALL RAMP		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type <b>DRIVER</b>	Name (Last,First,Mi) [REDACTED]	Address (Street, City, State, Zip) [REDACTED]	
	DOB [REDACTED]	Sex <b>F</b>	Injury <b>NO APPARENT INJURY</b>	Safety Equipment <b>UNKNOWN</b>
	Transported	Alcohol Test <b>No, Test Not Given</b>	Alcohol Test Result	

<b>UNIT 2</b>	Person Type	Name (Last,First,Mi)	Address (Street, City, State, Zip)	
	DOB	Sex	Injury <b>NO APPARENT INJURY</b>	Safety Equipment
	Transported	Alcohol Test	Alcohol Test Result	

V1 is a Chevrolet Traverse MN/LICLGN435 was attempting to park alongside the driver's side of the vehicle in the parking ramp at the Mall of America. V1 struck V2 (V2 is a Honda Odyssey MN/LIC ZDT389) along the left side of the rear bumper and fled without leaving her information. An unknown witness observed the incident and called MOA dispatch and advised on the suspect's plate. MOA security was able to locate V2 a few rows over in the same parking ramp with damage to the front right bumper, consistent with the damage done to V2. MOA had footage of the incident and it showed V1 striking V2 and leaving without attempting to leave information for the owner of V2.

Citation issued to driver of V1 (citation # 27012520232).